G. R. S. IX-5]

Previous references.

1921-22

(Misc)

File No. 22-21

Serial Nos. 1—2

Later references.

GENERAL AND REVENUE SECRETARIAT.

Serial Nos. 1—2

Part B for August 21

SUBJECT.

Estimate for the repairs of Sri Gopalakrishna Swami Temple at Nallavenkatanayakanpatti Village Dindigul

---

1045-47 & 22.8.21

To

The D. C. Hindu Rel. Comptroller & Madurai Region

Sanctions the ———

WD 1888—GPB—16,826—23-7-21

Kasthuri

G. R. S. 11) 1921-22.

GENERAL AND REVENUE SECRETARIAT.

(Mayuram)

NOTES.

File No. 22-21.1.

FILE HEADING.

Estimate for the repairs of Sri Gopalakrishnaswami Temple at Nonanimathur, Sirkar Zabti.

From

The Manager Supdt in c Mayuram.

Note No. Dated 12.7.21. Received 18.7.21.

Diary No. 112 Enclos 1 file Spare Copies Serial No. 1

BRIEF ABSTRACT OF LETTER.

Forwards for sanction a revised estimate for Rs. 1369 for the repairs of the above temple received from Rao Bahadur Supervisor, as the rates provided for certain items in the original estimate were inadequate owing to scarcity of labourers & rise in the price of materials, and recommends that in view

NOTES AND ORDERS.

of the local importance of the temples & the urgency of the repairs the cost of the estimate may be met from the State grant of the current official year.

The previous file (Mayu. 87-19) is put up for perusal.

The temple was inspected by the previous Manager Supdt Mr.

NOTES—First Sheet.

G. R. S. III-2]

General and Revenue Secretariat. | Mwz. File No. 22 of 1921-22.

Serial No.

Mr. by Arasamudu Iyengar and was found to be very badly in need of repairs.

In Govt order No. 2425-27/Mwz. 87-19-3 d. 13. 2. 20 an estimate for Rs. 78 was sanctioned for expenses in connection with the Kalakarshane ceremonies of the temple & a sum of Rs. 59-3- was sanctioned in G. O. No. 4048-51/Mwz. 87-19-5 d. 20. 5. 20 for the preparation of a wooden idol.

The present revised estimate for Rs. 1369 received from the A. C. for sanction has been countersigned by the Mawzai Inspdt only for Rs. 1160 since a sum of Rs. 209 included as Establishment charges at 18 per cent has been deducted as the work is to be carried out by the Revenue Dept. The estimate was also checked by the Executive Engineer, Tanjore Division.

Submitted for orders.

MM. 27.7.21. The Whole amt of Rs 1160 has been asked for from the State grant allotment.

RG 22-7-21

I think also that the temple. It is badly in need of repairs. The idol is

NOTE.—Contn. sheet.

G. R. S. III-2]

General and Revenue Secretariat. | Rees File No. 22 of 1921.

Serial No.

Beautiful one.
First Member 26/7/21

616-264
27-7

To debit the full amount to the Stategrant of the current year may cause some embarrassment. Cannot the expenditure be spread over two years? I do not anticipate any practical difficulty in doing this.
Rees
25/7/21.

May be done
First Member 28/7/21

683-331
29-7-21

approved
Rees
30.7.21 Draft 30/7/21

Draft order submitted.
M.V. 8.8.21. 8/8/21 Fair draft 15/8/21

Fair draft submitted.
M.V. 16.8.21. 16/8/21 Done 16/8/21

NOTE.—Contn. sheet.

General and Revenue Secretariat.

File No. 22 of 1921.

Serial No.	
2	No. 1045-7 dated 22nd August 21. From The D.C Amritsar & Comptroller & Audit Sanctions the estimate the Cost being met from the State Grant of the current year in equal proportions

2 C 2 iii

noted

GPB—800—14-7-15



OFFICE OF THE
MUZRAI SUPERINTENDENT
IN MYSORE.

NOTE.

SUBJECT. :-- Repairs to Sri Gopala-krishnaswami temple at Nonavinakere, -- Tiptur Taluk.

In continuation of my predecessor's Note R.C. No. 1347 dated 9th August 1919 regarding the repairs to the temple of Sri Gopalakrishnaswami and Sri Byataraya-swami at Nonavinakere, I beg to submit herewith a revised estimate for Rs. 1,369 for repairing the former institution and to state as follows:--

The estimates originally prepared having been found defective, the late Assistant Engineer Mr. C.B. Kasipathi - Sastry visited Nonavinakere and prepared a revised estimate for Rs. 892/- for repairing the temple of Sri Gopalakrishna-swami. This estimate was forwarded to the Deputy Commissioner for an expression of his opinion. He sent up a fresh estimate amounting to Rs. 1,369/- prepared by the Maramat Supervisor, the reason for the increase being that the rates for certain items provided for in the original estimate were inadequate in consequence of scarcity of labour and rise in the price

price of materials. The estimate having been sent to the Executive Engineer of the Tumkur Division, he is of opinion that the estimate provides for all items of work requiring to be urgently attended to and that the rates are in order.

2. The question of repairing this and the other institution has been pending for a long time and it cannot be deferred any longer without serious injury to the whole building. A ತಂಡ ದೇವಸ್ಥಾನ has been consecrated in pursuance of Government Order No. 4048-50/Muz.87-19-5 dated 20th May 1920 and no puja is being offered to the idol of Gopalaswami. In these circumstances, I beg to support the recommendation made by my predecessor Mr. G. -- . Aravamudiengar that the cost of the estimate may be met from the State Grant allotment of the current year.

3. In the estimate prepared by the Maramat Department, a sum of Rs. 209/- has been newly added as establishment charges at 18 per cent. This seems to be unusual as no establishment charges are being allowed on Muzrai estimates worked out by the Revenue Department. The estimate is therefore countersigned for Rs. 1160/- and submitted herewith for sanction. The estimate for repairing the temple of Sri Ryatarayaswami will be submitted separately for the orders of Government.

4. Correspondence ending with letter

letter No. 2866 dated 15th June 1921 from the Executive Engineer, Tumkur Division, is submitted for reference and kind return

Muzrai Superintendent.

12/7/21

G.R.S. VI–71]

SUBJECT Sanctions for Rs. 1160 an estimate for the urgent repairs of the Sri Gopala Krishnaswami temple at Nonavinakere, Tiptur Taluk, the cost being met from the State Funds of 1921-22 & 1922-23 in equal proportions ?

Diary No. of letter replied to 112 of 21-22.

Section Anzen

File No. 22 - - 21

Serial No. 2

General and Revenue Secretariat

( )

the 191

Proceedings of the Government of His Highness the Maharaja of Mysore.

Date of issue 22-8-21

Signed by Sri E.J. Bryce

Read— Note of the Amrai Supdt in Mysore dated 12th July 1921 stating that the Sri Gopala-Krishnaswami temple at Nonavinakere, Tiptur Taluk, was inspected both by the previous Amrai Supdt, Mr. G. Ananaswamy Iyengar and by himself and found to be very badly in need of repairs, that the question of repairing this institution has been pending for a long time and

Order Thereon No

May this be

i Printed ?

ii treated as a standing order ?

iii published in the Gazette, English Part ?

iv translated ?

v placed at the disposal of the press ?

vi published in the Gazette Kannada Part ?

and cannot be deferred any longer without serious injury to the whole building, and recommending that the estimate for Rs. 1369 drawn by the Deputy Comm[r] and scrutinised by the Executive Engineer may be sanctioned for Rs. 1160 deducting Rs. 209 provided for Establ[t] & tools and plant charges as the work will be carried out by Revenue agency, the charge being met from the State grant allotment of the current year.

List of enclosures.

Order No. 1045-7 Enclosed & returned
Irrig. 22-21-2 dt. 22.8.21

The estimate for Rs. 1160 is sanctioned, the cost being met from the State grant of the current and next official years (i.e., 1921-22 & 1922-23) in equal proportions.

Copied by

Examined by

WD 1744—GPB—30 000—17-8-19

G.R.S. 27]

GENERAL AND REVENUE SECRETARIAT.

(Continuation sheet draft form.)

2. The work should be carried out expeditiously under the supervision of the Taluk Amildar.

Secretary to Govt, Mauzai dept.
8/6/21

3.

The Mauzai Deputy in Mysore with the Board's estimate & other enclosures.

The Deputy Commr, Tumkur Dt.

The Comptroller to Govt, with a copy of the Abstract Estimate.

WD 1249—GPB 10,000—25-1-19

1045-7/Mmas 22-21-2 & 22.8.21

Abstract estimate of the probable cost of repairing the Sri Gopala-krishnaswami temple at Nonavinakere, Tiptur Taluk.

No.	Items of Work.	Per.	Rate. Rs.	A.	P.	Quantity.	Cost. Rs.	A.	P.
	I. MAIN TEMPLE.								
1.	Leakage repairs by inserting 2 courses of flat tiles, the lower one cement and the other with plastering the top line and after taking the present top plaster.	Sqt.	30	0	0	3.28	98	0	0
2.	Cement pointing	"	6	0	0	13.08	78	0	0
3.	Removing and revetting steps	...	Lumpsum			...	6	0	0
4.	Providing gates with iron bars to the entrance in patha-lankana	Sft.	2	0	0	78	156	0	0
	II. PAKASALA AND YAGASALA.								
1.	Providing a pulihore slab - stone	"	0	8	0	25	13	0	0
2.	Fixing the above after repair-ing the existing flat-stone	...	Lumpsum			...	5	0	0
3.	Repairs to the north wall of the Yagasala	...	Lumpsum			...	27	0	0
4.	Removing weeds and applying root-destroying solution	...	Lumpsum			...	5	0	0
	III. REMOVING AND RECONSTRUCTING THE GARBHAGUDI OF THE SRI GOPALAKRISHNASWAMI TEMPLE.								
1.	Removing the roof -- concrete and slab ...	Sft.	0	8	0	64	32	0	0
2.	Preparing the wooden box -- junglewood wrought and put up	Cft.	4	0	0	30.66	123	0	0
3.	Iron braces with bolts, nails including making charges etc. complete ...	...	Lumpsum			...	20	0	0
4.	Dismantling the slabbed walls of the temple	Cft.	0	4	0	432	108	0	0
5.	Rebuilding the wall with the slabs removed and setting in mortar and filling the gap - with concrete ...	Cft.	0	8	0	485	243	0	0
6.	Removing and replacing the -- beams and pillars	No.	2	0	0	6	12	0	0
7.	Replacing the covering slab and refoofing with 1 ft. fresh concrete with two layers of flat tiles with mortar	Sqr	40	0	0	0.64	26	0	0

8.	Cement pointing	Sqr.	6	0	0	1.99	12	0	0
9.	Reconstructing the parapet	Rft.	1	4	0	25	31	0	0
10.	Repairs to the floor	...	Lumpsum			..	10	0	0
11.	Testing foundation and -- closing the Ant-hill	...	Lumpsum			...	50	0	0
12.	Works of unforeseen items	...	Lumpsum			...	50	0	0
			Total			... ...	1105	0	0
	Contingencies @ 5 %					... ...	55	0	0
			Grand Total			...	1160	0	0

Rupees One Thousand One Hundred and Sixty only.

"C o p y".

Secretary to Government,

Muzrai Department.